

Card not being ejected on MJR-7000/8000

85 [Alex Nieves](#) Wed, Dec 22, 2010 [FAQ's](#), [FAQ's](#) 3 10438

Why wont the card eject after its pulled in the MJR-7000/8000?

Answer:

A common problem would be the DC Motor (p/n [IR-630770](#)). This is the motor that moves the carriage side to side. Sometimes just taping the clock on the right side will cause the card to eject. This is an indication of a faulty motor. Replace motor and test.

Online URL: <http://tkb.amano.com/article.php?id=85>