All employee including supervisor is unable to punch on the handpunch terminal

153 Frank Mateo Wed, Mar 23, 2011 HandKey Terminals, Time Guardian Version 4.0 or Lower 0 5835

AMANO.

Introduction

Attached are steps to remedy an issue where all employee including supervisor is unable to punch on the hand punch terminal. Make sure to poll the clock before following the steps and receive maps from the hp commands - terminal settings. The steps will set the clock to factory default which will erase all data in the clock only. You may then try a send maps to restore them but this is not a guarantee.

Note: This guide applies to Time Guardian version 4 or lower

Conclusion

Thank you for your time, and have a great day. As always, feel free to submit ideas on topics you want addressed in the Amano Knowledge Base using the comments feature.

Amano Cincinnati, Inc. reserves the right to make equipment changes and improvements which may not be reflected in this article. Portions of this article may have been updated to include the latest hardware or firmware version, if applicable. Amano assumes no liability for errors and/or omissions. If you should find any errors or unclear information, please notify Amano by posting a comment.

Customer Support Information	Call toll-free in the U.S.: 800-253-9836 (outside U.S. call 973-364-0294) or Fax: 973-364-1091 Mailing address: Amano Cincinnati, Inc., 140 Harrison Ave., Roseland, New Jersey 07068 Web site: www.amano.com/time • E-mail: support@amano.com

Online URL: http://tkb.amano.com/article.php?id=153