PIX-55 PRT E2 Error

398 <u>David Lopez</u> Mon, Nov 7, 2011 <u>PIX-55 Atomic Clock</u> 0 4980

AMANO.

Introduction

PIX-55 giving PRT E2 error.

Try checking the cables inside of the clock make sure they are plugged in all the way and not loose. If this is the case try unplugging the clock then plug it back in. If this fails to clear the error, please call support.

800-253-9836

Conclusion

Thank you for your time, and have a great day. As always, feel free to submit ideas on topics you want addressed in the Amano Knowledge Base using the comments feature.

Amano Cincinnati, Inc. reserves the right to make equipment changes and improvements which may not be reflected in this article. Portions of this article may have been updated to include the latest hardware or firmware version, if applicable. Amano assumes no liability for errors and/or omissions. If you should find any errors or unclear information, please notify Amano by posting a comment.

Customer Support Information Call toll-free in the U.S.: 800-253-9836 (outside U.S. call 973-364-0294) or Fax: 973-364-1091 Mailing address: Amano Cincinnati, Inc., 140 Harrison Ave., Roseland, New Jersey 07068 Website: www.amano.com/time • E-mail: support@amano.com

Online URL: http://tkb.amano.com/article.php?id=398