

How to resolve CP-5000 overprint problem

70 [Raj Desai](#) Thu, Dec 23, 2010 [FAQ's](#), [How To's](#), [Tricks](#), [Tips](#) 0 3766

How to resolve CP-5000 overprint issue?

Answer:

Replace the ink ribbon cartridge part#CE-316452

Online URL: <http://tkb.amano.com/article.php?id=70>