
## MTX-15 contrast setting discontinued

566 Frank Mateo Wed, Jul 5, 2017 MTX-15 Terminal 0 6615

## AMANO.

## Introduction



This feature has been removed on firmware version 3.0. The standard factory contrast has been found to be acceptable on all environments with proper lighting. If you have contrast issues, try erasing your clock to factory default. Steps can be found using keyword search "e03" in this website. If you still have contrast issues thereafter, your unit may need to be serviced.

800 896 7035

## Conclusion

Thank you for your time, and have a great day. As always, feel free to submit ideas on topics you want addressed in the Amano Knowledge Base using the comments feature.

Amano Cincinnati, Inc. reserves the right to make equipment changes and improvements which may not be reflected in this article. Portions of this article may have been updated to include the latest hardware or firmware version, if applicable. Amano assumes no liability for errors and/or omissions. If you should find any errors or unclear information, please notify Amano by posting a comment.

Customer Support Information

Call toll-free in the U.S.: 800-253-9836 (outside U.S. call 973-364-0294) or Fax: 973-364-1091 Mailing address: Amano Cincinnati, Inc., 140 Harrison Ave., Roseland, New Jersey 07068 Web site: www.amano.com/time • E-mail: support@amano.com

Online URL: <a href="http://tkb.amano.com/article.php?id=566">http://tkb.amano.com/article.php?id=566</a>